



A LAFRANCE AID

BULLETIN

AMERICAN LAFRANCE CORPORATION

ELMIRA, NEW YORK

March 15, 1956

Subject Pump Panel Gauge Compartment

If you are having any difficulty with the pump panel gauge compartment fogging or if the black background on the panel glass shows signs of deteriorating, this can be eliminated by drilling (2) 1/4" holes on the inside of the gauge compartment.

These holes should be towards the bottom of the compartment and they will afford proper ventilation to correct this condition.

L. C. LaVelle
M.F.A. Service Manager.